



Crankshaft Components, Inc.

Falcon Crankshaft Components, Inc.
1115 Old Coachman Road
Clearwater, FL 33765
United States of America
Tel 727-797-2468
Fax 727-796-3132
www.falconcranks.com

Yamaha FJ 1100 / FJ 1200 Inner Hub Modification for Billet Hub

The following must be done when using our billet hub.

